

FIG. 1




FIG. 2




FIG. 3






FIG. 4


FOURTH STEP



FIFTH STEP



SIXTH STEP




TO SEVENTH STEP


0050495-10000

FIG. 5

SEVENTH STEP



EIGHTH AND  
NINTH STEP



COMPLETE

FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14






FIG. 15





FIG. 16



000001 9070000

FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21





FIG. 22



000001-3046300

FIG. 23




FIG. 24




FIG. 25




FIG. 26a




FIG. 26b




FIG. 27






FIG. 28




FIG. 29




FIG. 30




FIG. 31




FIG. 32




FIG. 33a




FIG. 33b




FIG. 34a




FIG. 34b





FIG. 35



000001 3043300

FIG. 36




FIG. 37




FIG. 38




FIG. 39a




FIG. 39b






FIG. 39c




000001 50436300



# FIG. 40



# FIG. 41



PHYSICAL VALUES AND SPUTTER RESISTANCE OF STRESS RELAXATION LAYER CANDIDATE MATERIAL  
 (X: OCCURRENCE OF CRACKS,  $\Delta$ : OCCURRENCE OF WRINKLE,  $\circ$ : NO ABNORMALITY)